




**SCRAM**  
GPS

# Charging Instructions


Only use the provided SCRAM GPS Charger. Connect one end of the charger to a wall outlet.



Connect the other end of the charging cable to the bracelet by sliding the terminal into the slot in the device housing.




When connected correctly, the bracelet will vibrate for two (2) seconds, and a **blinking green light** will appear on the top of the device. Leave the charging cable connected until the blinking green light turns **solid green**.



## Charge Indicator Lights

Charging – Blinking Green Light



Charge Complete – Solid Green Light



Not Charging – No Green Light






**SCRAM**<sup>®</sup>  
G P S

# Instrucciones de Carga


Utilice únicamente el cargador GPS SCRAM incluido. Conecte un extremo del cargador a una toma de corriente.



Conecte el otro extremo del cable de carga a la pulsera deslizando el terminal en la ranura de la carcasa del dispositivo.




Una vez conectada correctamente, la pulsera vibrará durante dos (2) segundos y se encenderá una luz verde intermitente en la parte superior del dispositivo. Deje el cable de carga conectado hasta que la luz verde intermitente se vuelva verde fija.



## Luces indicadoras de carga

Cargando – Luz verde intermitente



Carga Completa – Luz verde fija



No carga – No hay luz verde

